

Appendix A-1. Representative Project Site Photographs



**Photo 1.** Aerial view of northern portion of Project site – looking northeast  
(May 14, 2021)



**Photo 2.** Aerial view of northeastern portion of Project site – looking southeast  
(May 14, 2021)



Appendix A-1. Representative Project Site Photographs



**Photo 3.** Existing access road along west boundary of Project site – Mellin Levee through center of photo along fence line to west of access road  
(May 4, 2022)



**Photo 4.** Looking east from western Project boundary at grassland and clay flat habitat  
(August 5, 2022)



Appendix A-1. Representative Project Site Photographs



**Photo 5.** Looking west across Project site at managed marsh habitat  
(August 5, 2022)



**Photo 6.** Looking west across Project site at irrigated pasture  
(March 14, 2019)



Appendix A-1. Representative Project Site Photographs



**Photo 7.** Looking east along Watson Hollow Slough and adjacent berm along northern boundary  
(August 5, 2022)



**Photo 8.** Existing utility line in northern portion of Project Site (to be removed)  
(August 5, 2022)



Appendix A-1. Representative Project Site Photographs



**Photo 9.** Existing utility line in northern portion of Bank property  
(August 31, 2023)



**Photo 10.** Looking east at location of proposed low water crossing and tidal channel  
(August 31, 2023)



Appendix A-2. Representative Photographs of Offsite Utility Improvement Work Areas (June 25, 2024)



**Pole #1 and Pull Site**

Location: 38.188459, -121.674041

Habitat in Work Area: Non-native grasses/ruderal

Sensitive Habitat Nearby: Emergent marsh and open water



**Pole #2**

Location: 38.188386, -121.675020

Habitat in Work Area: Non-native grasses/ruderal, blackberry

Sensitive Habitat Nearby: Emergent marsh and open water



**Pole #3**

Location: 38.188380, -121.676054

Habitat in Work Area: Non-native grasses/ruderal

Sensitive Habitat Nearby: Emergent marsh and open water



**Pole #4**

Location: 38.188381, -121.677127

Habitat in Work Area: Non-native grass/ruderal

Sensitive Habitat Nearby: Emergent marsh and open water



Appendix A-2. Representative Photographs of Offsite Utility Improvement Work Areas (June 25, 2024)



**Pole #5**

Location: 38.188369, -121.678175

Habitat in Work Area: Non-native grass/ ruderal

Sensitive Habitat Nearby: Emergent marsh, open water



**Pole #6**

Location: 38.188370, -121.679221

Habitat in Work Area: Non-native grass/ ruderal

Sensitive Habitat Nearby: Emergent marsh, open water



**Pole #7**

Location: 38.188365, -121.670233

Habitat in Work Area: Non-native grass/ruderal

Sensitive Habitat Nearby: Emergent marsh and open water



**Pole #8**

Location: 38.188368, -121.671173

Habitat in Work Area: Non-native grass/ ruderal

Sensitive Habitat Nearby: Emergent marsh and open water



Appendix A-2. Representative Photographs of Offsite Utility Improvement Work Areas (June 25, 2024)



**Pole #9 and pull site**

Location: 38.188375, -121.682164

Habitat in Work Area: Non-native grass/ruderal

Sensitive Habitat Nearby: Emergent marsh and open water



**Pole #10 (near Highway 84)**

Location: 38.183025, -121.666647

Habitat in Work Area: Non-native grass/ruderal

Sensitive Habitat Nearby: Emergent marsh, open water, riparian



**Proposed Access Road** – easternmost access road on existing graveled farm road



**Proposed Laydown Area** - Disturbed area formerly used for staging farm equipment and hay